


GO AND NOT GO RING THREAD GAUGES**ČSN 25 4025**
ČSN 25 4035

For Metric Threads



The ring thread gauges are used for checking of screw threads according to ČSN 014013. In standard version for M5-M100 with rough (basic) and fine lead for right-hand threads with the 4H, 6H, 6E, 6G fit and of selected size with the 8g fit according to ČSN ISO 965-1, ČSN ISO 965-2 and ČSN ISO 965-3. In special version, the gauges for threads over M100, threads of other leads from 0.5 inclusive, left-hand threads and other fit of threads, are available.

For checking of wear of go (ČSN 254025) and not go (ČSN 254035) ring thread gauge are used reference plug gages (ČSN 254029, 254039).

Legend:

d nominal dimension
L, L1 ... width of the ring thread gauge